J10/2/6950



## SOUTH AFRICAN CIVIL AVIATION AUTHORITY

## **ACCIDENT REPORT - EXECUTIVE SUMMARY**

Date of Accident	23/09/1998	Time of Accident		0545z		
Aircraft Registration	ZS-LRX	Type of Aircraft		Piper PA 34-200		
Pilot-in-command Licence Type		Transport pilot		Licence Valid	Yes	
Pilot-in-command Flying Experience		Total Flying Hours	4095 hours	Total Hours on Type	380 hours	
Type of Operation		Training				
Last point of departure		Port Alfred Aerodrome				
Next point of intended landing		Port Alfred Aerodrome				

Location of the accident site with reference to easily defined geographical points (plus GPS readings if possible)

On Runway 28 at Port Alfred Aerodrome.

Meteorological Information	eorological Information Weather was reported to be fine.				
Number of people on board	2 + 2	No. of people injured	Nil	No. of people killed	Nil
Synopsis					

The instructor was engaged in the final session of a multi-engine conversion. They had completed three normal full load and two asymmetric approaches. The final landing was a glide approach commencing at 3500 feet overhead the airport with the throttles set to zero thrust condition.

Approaching the point where the student should have started to flare, the instructor noticed the speed was approximately 5 mph below the target speed of 105 mph. He noticed the student was aware of the situation and reminded her of the low power setting. When the student failed to increase power he attempted to cushion the landing by advancing the throttles and pulling back on the control column, but it was too late. The aircraft landed heavily, the undercarriage collapsed and it slid for about 200 meters on the runway until it came to rest.

## **Probable Cause**

The student failed to maintain the correct airspeed and technique during the practised forced landing and the instructor did not timeously intervene.