

EXECUTIVE SUMMARY - AIRCRAFT ACCIDENT REPORT

					Reference:	CA18/2/3/	7751
Aircraft Registration	ZU-BLW	/	Date of Accident	07 Ja	anuary 2004	Time of Accide	nt 0545Z
Type of Aircraft	Aviatika 89	0 CS	Н	Type of Operation		Private	
Pilot-in-command Licence Type		Private	Age	39	Licence Valid	Yes	
Pilot-in-command Flying Experience		Total Flying Hours		1205.0	Hours on Type	130.0	
Last point of departure Rie		Rietspruit Farm Private Aerodrome near HBV					
Next point of intended landing Rie		Rietspruit Farm Private Aerodrome near HBV					
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)							
At Platkoppie private farm							
Meteorological Inform	ation CA	CAVOK, Wind: Nil, Temperature: 28°C, Clouds: Nil.					
Number of people on	ole on board 1 + 0 No. of people inju		ired	1 N o	o. of people killed	0	
Synopsis					•		
The cilet stated the	نا ام مما ا		a and a last a all the account		مالحة ماميد ميث		

The pilot stated that he had just completed the crop spraying detail and decided to fly over his farm to inspect his dams, when suddenly the engine lost power and it subsequently failed. Efforts to restart the engine failed. He then elected to execute a forced landing on a maize field but, he could not clear the clump of trees in his flight path and he collided with them.

The pilot sustained minor injuries to his leg and the aircraft was destroyed during the impact sequence.

The last Annual Inspection was carried out on 29 January 2001 at 120.0 flying hours. The aircraft was flown for a further 10 flying hours after the Annual Inspection. No maintenance was done on the aircraft for two years (viz, 2002 and 2003) and yet the pilot flew the aircraft for 10 hours before the accident. The pilot knowingly flew an aircraft, which did not have a valid Authority to fly.

The pilot recovered the aircraft prior to the investigator getting on site. The investigators investigation on the engine revealed fuel in the carburettor bowls, fuel filters, no damages to the engine and the engine was then test run. The engine started and run with no difficulty albeit it could not run at full power due to damaged engine mounts.

Probable Cause

Unsuccessful forced landing as a result of an undetermined engine power loss and a subsequent engine failure.

Contributory

Failure to carry out maintenance.

IARC Date		Release Date	
-----------	--	--------------	--

CA 12-13a	23 FEBRUARY 2006	Page 1 of 1
-----------	------------------	-------------