Section/division Occurrence Investigation

## AIRCRAFT ACCIDENT REPORT AND EXECUTIVE SUMMARY

Form Number: CA 12-12a

						T			
					Reference:	CA18/2/3/8987			
Aircraft Registration	ZS-RDG		Date of Accident	29 November 2011		Time of Accider	ot 0620Z		
Type of Aircraft	Robinson R44 R		taven II – Helicopter Type o		of Operation	Private			
Pilot-in-command Licence Type		Private	Age	45	Licence Valid	Yes			
Pilot-in-command Flying Experience		Total Flying Hours	201.7		Hours on Type	86.1			
Last point of departure Wo		onderboom Aerodrome (FAWB), Gauteng Province							
Next point of intended landing Wor		onderboom Aerodrome (FAWB), Gauteng Province							
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)									
East of Runway 06 at Wonderboom Aerodrome (FAWB), Gauteng Province, GPS S2539.741 E02813.171 Elevation 4111 feet									
Meteorological Inform	sation Su	Surface wind: 030°/10 knots gusting 15kts; Temperature: 22℃; Visibility: Good							
Number of people on	board	1+3	No. of people in	jured	0 <b>N</b> o	o. of people killed	0		
Synopsis					•				

The pilot accompanied by three passengers was on a local private flight from Wonderboom Aerodrome with the intention of landing back again at Wonderboom Aerodrome.

The pilot stated that during take-off, vertical ascent and hover he carried out the normal parameter checks and as he started the forward flight, the helicopter suddenly drifted to the right with the helicopter's nose in a nose down attitude. He then attempted to correct the situation with the left cyclic, but the helicopter sank back towards the ground. The right hand skid first made contact with the ground causing a dynamic rollover onto the right hand side.

According to the available weather information with the surface wind direction 030°/10kt, gusting 15kt, the take-off was executed with a crosswind component of 60° from the left hand side.

The helicopter sustained substantial damage to the skids, main rotor, tail rotor, tail boom and fuselage.

The occupants sustained no injuries during the impact sequence.

## **Probable Cause**

During take-off whilst in the ascent and hover with crosswind conditions from the left, the pilot lost control of the helicopter and the skids impacted the ground followed by a dynamic roll over.

IARC Date	Release Date	

CA 12-12a <b>23 FEBRUARY 2006</b>	Page 1 of 1	1
-----------------------------------	-------------	---