Ref: 7429



## SOUTH AFRICAN CIVIL AVIATION AUTHORITY ACCIDENT REPORT – EXECUTIVE SUMMARY

			ı			1			
Aircraft Registration	ft Registration ZU-CJG		Date of Accident	14 Nov 2001 <b>T</b>		Time	of Accident	0900Z	
Type of Aircraft	MAGNI GYRO			Type of Operation			n Private		
Pilot-in-command Licence Type			Gyrocopter	Age	51	Li	cence Valid	Yes	
Pilot-in-command Flying Experience		Total Flying Hours Flying hours Past 90 Days Flying Hours on Type Past 90 Days	157.9 75.9 75.9			otal Flying ours on Type	75.9		
Last point of departure Mar		argate							
Next point of intended landing Cate		ato Ridge							

Location of the accident site with reference to easily defined geographical points (GPS readings if possible)

## Hibberdene

Meteorological Information	Fine weather conditions prevailed with the wind in a north-easterly direction at 25 kt. The visibility was good and the temperature approximately +25°C with no cloud cover.									
Number of people on board	1+1	No. of people injured	1 Minor	No. of people killed	0					
Synopsis										

On 14 November 2001, at approximately 0850Z, the pilot and a passenger took-off from Margate for a private flight, along the coastline, to Hibberdene.

The pilot stated that at 0950Z, near Hibberdene, he was flying at 100 ft AGL, looking down, and flew into power lines.

During the emergency landing on the N2 highway, the aircraft rolled over, causing substantial damage to the rotor, rotor head, propeller, tail unit and instruments.

The correctly licenced pilot sustained minor injuries and the passenger escaped unharmed.

According to available documentation the gyrocopter was correctly maintained.

Fine weather conditions prevailed at the time of the accident.

## **Probable Cause**

The pilot stated that he flew into power lines while flying at 100 ft AGL. At the time of the accident he was looking down and not forward.