Ref: 7703



SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT - EXECUTIVE SUMMARY

Aircraft Registration	ZU-CZI		Date of Accident		21 September 2003		Time of Acciden		nt	1300Z	
Type of Aircraft	MAGNI-GY	'RO I	и 16		Type of Operatio		n Private				
Pilot-in-command Licence Type			Private		Age	61	Li	cence Valid	Yes		
Pilot-in-command Flying Experience			Total Flying Hours	3	85.9			ours on Type	28.2		
Last point of departure			Mafikeng Aerodrome								
Next point of intended landing			Private Aerodrome near Maretsane district								
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)											
Private Aerodrome (Maretsane district)											
Meteorological Inform	ation Fir	Fine, wind North Westerly at 12kt, Temperature 32°C, visibility good									
Number of people on	board 1		No. of people	in	jured	Nil N		No. of people killed		Nil	
Synopsis											

During the take-off roll in a westerly direction, the pilot experienced a sudden gust of wind from the right (NW). He was unable to maintain directional control and the aircraft veered off the runway to the left where it overturned and came to rest against the aerodrome fence.

Substantial damage was caused to the main rotor blades and main rotor head. The right main landing gear also failed and the propeller was damaged as well as the cockpit area.

The pilot, who was the sole occupant of the aircraft, did not sustain any injuries.

The total Airframe hours at the time of the event was 85.9 hours since new.

The aircraft had a valid Authority To Fly at the time of the accident which was issued on 28 March 2003.

Probable Cause

The pilot experienced a strong gust from the right during the take-off roll, which he did not anticipate, resulting in a loss of directional control which caused the aircraft to depart to the left of the runway and overturn.